



[www.qorvo.com](http://www.qorvo.com)

## PAC EVK Quick Start: Hardware Setup

00:00:07.840 --> 00:00:08.520  
Hey, everyone.

00:00:08.520 --> 00:00:13.200  
My name is Jonathan De Luna-Rodriguez,  
one of control applications engineer

00:00:13.200 --> 00:00:16.600  
here at Qorvo in the Power Management  
Motor Control team.

00:00:17.240 --> 00:00:21.240  
This video is a getting started  
using PAC, walking through the hardware

00:00:21.240 --> 00:00:24.240  
setup and first power up for Qorvo's

00:00:24.360 --> 00:00:27.120  
PAC Motor Control Evaluation Kits.

00:00:27.120 --> 00:00:29.880  
The goal here is to walk  
through the connections, show

00:00:29.880 --> 00:00:35.400  
how to power the board for the first time,  
and confirm everything looks normal.

00:00:35.560 --> 00:00:38.200  
For this video, no motor spinning just yet.

00:00:38.200 --> 00:00:41.520  
Some quick context  
on what these evaluation boards are for.

00:00:42.000 --> 00:00:45.400  
PACs EVKs are designed to help you  
evaluate the PAC device

00:00:45.400 --> 00:00:49.200  
in a real motor control  
set-up and start development immediately.

00:00:49.720 --> 00:00:54.200  
They expose key device signals to headers  
for probing and integration.

00:00:54.720 --> 00:01:00.440

© 2024 Qorvo US, Inc.



They provide PC connectivity over  
UART as a virtual comport, or GUI control

00:01:00.640 --> 00:01:05.840  
and monitoring and support  
programming and debugging through SWD

00:01:08.600 --> 00:01:10.840  
So here's what you need on the bench.

00:01:10.840 --> 00:01:13.560  
An EVK, each EVK will include

00:01:13.560 --> 00:01:17.920  
an ET-UARTSWD module board, two four pin

00:01:17.920 --> 00:01:21.000  
connectors, and a micro USB cable.

00:01:22.080 --> 00:01:24.800  
Next, you will need a brushless DC motor

00:01:24.800 --> 00:01:27.960  
or a permanent magnet synchronous motor,

00:01:28.920 --> 00:01:35.200  
a DC bench supply, and a SWD debugger  
such as J-link.

00:01:35.960 --> 00:01:38.400  
Here's a high level EVK walk through.

00:01:38.400 --> 00:01:42.600  
I'll be using the PAC55724  
EVK as the example.

00:01:43.000 --> 00:01:47.640  
But basically any PAK more control f k  
you'll find these connection points.

00:01:48.120 --> 00:01:51.480  
So firstly the PAC55724 device

00:01:51.480 --> 00:01:54.200  
IC is right in the center

00:01:54.200 --> 00:01:57.440  
You have your motor phase outputs U, B  
and W.

00:01:57.720 --> 00:02:01.160  
This is where you connect



your brushless DC motor.

00:02:01.680 --> 00:02:04.200

You have your power inputs Vin

00:02:04.200 --> 00:02:07.200

and ground. Using SPADE terminals.

00:02:07.440 --> 00:02:09.840

You have your SWD header.

00:02:09.840 --> 00:02:11.920

This is where you connect the SEGGER J-Link

00:02:11.920 --> 00:02:14.080

for programing and debugging.

00:02:15.280 --> 00:02:16.960

The UART connector here

00:02:16.960 --> 00:02:20.480

which will be used to communicate  
with the PAC FOC GUI.

00:02:21.240 --> 00:02:24.000

You'll also find the DC-to-DC buck converter

00:02:24.000 --> 00:02:27.040

components down here as highlighted below.

00:02:27.600 --> 00:02:30.600

And hall sensor inputs on this channel  
block.

00:02:31.440 --> 00:02:34.320

One quick note when using hall sensors is

00:02:34.320 --> 00:02:37.320

that you'll need to apply jumpers.

00:02:37.320 --> 00:02:40.320

A jumper one, two and three,

00:02:40.320 --> 00:02:42.240

shown labeled on the board.

00:02:42.240 --> 00:02:45.240

This is for hall mode operation.

00:02:45.600 --> 00:02:49.800

Let's take a closer look and walk you  
through the connections in the lab bench.



00:02:50.160 --> 00:02:53.400  
Let's walk through the required  
connections for the evaluation board.

00:02:53.800 --> 00:02:56.560  
So before flashing the firmware  
or opening the GUI,

00:02:56.560 --> 00:02:59.560  
you need to make sure everything is wired  
correctly.

00:02:59.640 --> 00:03:01.800  
The first step is connecting to the DC

00:03:01.800 --> 00:03:04.400  
power supply as shown here.

00:03:04.400 --> 00:03:06.920  
Vin and ground on the PAC55724.

00:03:06.920 --> 00:03:09.920  
For this device.

00:03:10.320 --> 00:03:13.680  
It should not exceed the absolute  
max voltage of 60 volts.

00:03:14.160 --> 00:03:16.680  
It is optimized to operate with voltages  
ranging

00:03:16.680 --> 00:03:19.680  
from 14V to 36V nominal.

00:03:19.960 --> 00:03:23.160  
For my case, I'll stick with 20V  
as shown in the power supply.

00:03:24.160 --> 00:03:25.000  
When power is

00:03:25.000 --> 00:03:28.360  
applied,  
you should see the Vin LED turn on,

00:03:29.040 --> 00:03:32.040  
as well as the 5V LED.

00:03:33.120 --> 00:03:36.120  
Second step is connecting the J-Link debugger.

© 2024 Qorvo US, Inc.



00:03:36.560 --> 00:03:39.560  
It uses a four pin SWD cable.

00:03:39.720 --> 00:03:41.080  
Make sure to match the polarity

00:03:41.080 --> 00:03:44.400  
between the isolator board  
and the evaluation board.

00:03:45.000 --> 00:03:49.880  
So this is used for downloading the  
firmware and debugging the PAC device.

00:03:50.480 --> 00:03:53.480  
Third step  
is connecting the UART interface.

00:03:53.720 --> 00:03:56.720  
It also uses a four pin jumper cable.

00:03:57.000 --> 00:03:59.560  
Make sure to match the polarity.

00:03:59.560 --> 00:04:02.080  
This is what's used to communicate

00:04:02.080 --> 00:04:05.360  
with the PAC FOC GUI over a COM port.

00:04:06.360 --> 00:04:09.040  
At this point,  
you should now have your power connected,

00:04:09.040 --> 00:04:12.040  
your J-Link connected,  
and your UART connected.

00:04:12.640 --> 00:04:15.360  
Now the hardware is ready  
and we can move on to the firmware

00:04:15.360 --> 00:04:17.040  
installation and tool setup.